The following is a list of added features and issues fixed in the VIGIL Video Management System software suite between VIGIL v12.00.0300 (June 13th, 2022) and the new release of VIGIL v12.00.0400 (September 16th, 2022). Each VIGIL product will be listed with its fixed issues and added features contained beneath it in the table. Please contact 3xLOGIC Engineering Support if you have any questions or concerns.

Column Explanation:

- **Ticket #.** – The listed issue's reference number
- **Issue/Enhancement** – Description of the issue/enhancement

VIGIL Server - Includes VIGIL Video Verification, VIGIL Media Server, VPOS

Ticket #.	Issue/Enhancement
Added Features	
299929	Added a hidden regkey to allow us to tweak the max time size of recorded MJP files to be more than a minute
299120	Removed *Use VGA Hardware Acceleration* setting
298068	Added configurable startup delay for Gen III capture cards (disabled by default).
296440	Removed Max Allowed PCI Bandwidth setting and force 'Unrestricted'.
296437	Added behavior for ignoring analog channel signal state
296122	Removed Max Total IP Camera FPS setting
295335	Added Retry Button to VIGIL Video Viewer
Issues Fixed	
298036	Fixed issue where Connection Settings > 'Data' tab missing text when UDP is selected
294899	Fixed service issue where sp_check_tables stored procedure was being excessively called
294904	Fixed service issue where sp_check_footage stored procedure was being excessively called
295425	Fixed issue where the Ruby 2.01 UDP Listener *Payouts* were not logging value
295152	Fixed issue where IP Cameras could not be successfully configured on Channel 92.

VIGIL Client

Ticket #.	Issue/Enhancement
Issues Fixed	
299963	Fixed issue with poor client UI performance in during high-framerate playback
296397	Fixed issue where VIGIL Client was not visible in Windows Add/Remove programs
296396	Remove VIGIL Remote Updater from VIGIL Client install kits.
295039	Fixed issue where Client managed by VCM mode is broken with Active Directory enabled

VIGIL Central Management (VCM)

Ticket #.	Issue/Enhancement
Added Features	
299325	Added reporting of SSD wear information
Issues Fixed	
295052	Fixed issue where some VCM updates run twice
296403	Fixed issue where correct version was not updating in control panel

3x

V120400RN-1 Updated: 9/13/2022

VISIX IP Setup Utility

Ticket #. **Issue/Enhancement**

Issues Fixed

299095	Fixed issue with utility saving SURROUND camera channel number incorrectly
299093	Fixed issue with utility saving SURROUND camera URL incorrectly

VIGIL DV Player

Ticket #. **Issue/Enhancement**

Added Features

299536	Added toggle for forcing system memory video surfaces

V120400RN-1 Updated: 9/13/2022