

VIGIL VMS 13.00.0000 - Full Release Notes

The following is a list of added features and issues fixed in the VIGIL Video Management System software suite between VIGIL v12.60.0500 (June 2024) and the new release of VIGIL v13.00.0000 (December 2024). Each VIGIL product will be listed with its fixed issues and added features contained beneath it in the table. Please contact <u>3xLOGIC Engineering Support</u> if you have any questions or concerns.

Column Explanation:

- Ticket #. The listed issue's reference number
- **Issue/Enhancement** Description of the issue/enhancement

VIGIL Server- Includes VIGIL Video Verification, VIGIL Media Server, SVCVigil, VIGIL Kits

Ticket #.	Issue/Enhancement
Added Features	
86452	Implemented GKS Omni Parser
86409	Reworked Digital Presets UI to improve user experience.
85942	Added support for polling media wear out indicator from WD NVMe drives
84700	Preliminary integration for VCA Server
82074	Added option in VSMU to disable "X" close button on VIGIL Client window whilst in Kiosk mode
79799	Made ONVIF camera information digestible for VCM
79742	Appended Date (MM/DD/YYYY) to receipt number for Aloha 6.7 IP Parser
79244	Updated NCR Radiant parser for optimized handling of loyalty cards for Inner Circle
78928	Improved behavior between Audio Recording/Talk checkboxes, Audio Recording/Talk Devices, and Audio Coupling options
77977	Added SCO C18 Terminal Support to Verifone Ruby parser
77970	Updated and modernized VIGIL installation and upgrade packages
77951	Improved axis analytics support
77950	Added support for ingesting ANPR data from applicable VISIX Gen III Cameras.
77730 / 75215	Add support for configuring VCA Rules and settings on Gen III cameras via VSMU.
77114	Improved Network Camera Settings/Camera Control checkbox behavior
76724	Reworked VIGIL system tray app
75750	Increased retention of diagnostic logs
75214	Changed codec to G.711 between VIGIL client and server
75140	Added AAC audio codec support
74979	Improved performance of analytics object metadata updates
74709	Converted Retalix POS parser from external application into an internal VIGIL Server POS parser
73845	Added support for multiple VCA sources from the VX-20M-SURROUND-OD-RIAW-X camera
73844	Added full support for new VISIX camera models: VX-12M-360-IAW-X VX-12M-360-IAW VX-5M-OT-RIW VX-5M2-0T-RIW VX-5M20-B-RIAL-X VX-5M20-B-RIAL-X VX-8M-180-IAW-X VX-20M-SURROUND-OD-RIAW-X VX-20M-SURROUND-OD-RIAW VX-10M28-DUAL-OD-IAW-X VX-10M28-DUAL-OD-IAW VX-10M4-DUAL-OD-IAW VX-10M4-DUAL-OD-IAW VX-5M-0B-CL-RIAW-X VX-5M-OT-CL-RIAW-X VX-5M28-MD-IAW-02(-X)
65805	Allow reordering of cameras in Camera Setup tab

www.3xlogic.com | helpdesk@3xlogic.com

© 2007-2024 3xLOGIC, Inc. All rights reserved. Information in this document is subject to change without notice. 3xLOGIC, and the 3xLOGIC/ VIGIL logos are trademarks of 3xLOGIC, Inc. All other trademarks are the property of their respective owners.

Issues Fixed	
88260	Corrected spelling of Gilbarco Passport XML in VSMU > POS/ATM Connection Type drop- down.
88031	Fixed issue where 1fps / RecordSpeed / Set by Camera Speed Registry Keys are not respected when Server is restarted.
86754	Fixed issue where switching to Relays/Alarms tab enables Apply button even if no new changes are present
86753	Fixed issue where POS Alarm Output Relay list not updating when digital outputs change
86598	Fixed issue where, when Force connections to use port 22703 is set, remote client over relay gets a warning about duplicate Aliases
86223	Fixed issue causing VSMU to crash on launch due to problem with HIK Capture Card Image Level sliders.
85456	Fixed issue with Gen III camera ONVIF PTZ zoom control reacting slowly to inputs.
85423	Fixed issue where channel 76 sub-stream was failing
85402	Fixed issue allowing 'Max Other Connection Setting' / 'MaxDefaultConnections' to be set to 0
84871	Fixed issue with priority camera mappings failing
84583	Adjusted 'Unsaved Changes' warning pop-up button strings for clarity.
84272	Restored Arecont 180 Stitched Panoramic V2 settings UI
84225	Fixed issue where VVV cannot connect to older non-encrypted All-In-One cameras.
83552	Fixed issue where settings can fail to load for VSMU if null values are present in dio_mailsettings table
82752	Fixed issue with inconsistent default values in POS / ATM Connection Settings UI
82528	Fixed issue causing Axis audio device SIP audio talk to fail.
80995	Fixed issue where No NIC error does not display in VIGIL Register even when no NIC is present
80794	Fixed issue where Gen IIII PTZs can't be controlled / moved in Virtual Switch due to issue with joypad scaling.
78798	Fixed issue where setting up an Axis Audio recording Device changes the RTSP Port to 80 when it should be 554
78663	Fixed issue where the incorrect subnet mask is displayed in 'Change IP address' window when detecting by ONVIF SDK
77929	Fixed issue with Display options failing for On-board analytics.
75988	Fixed issue where the 'Scheduled still shots' window will not allow you to close it unless you have selected a camera
74842	Fixed issue where VIGIL Connect direct connection configuration info link was dead
73286	Fixed issue where Remote Web interface allowed panning outside of the target content, revealing Windows UI

VIGIL Client

Ticket #.	Issue/Enhancement
Added Features	
85643	Added support for Auto Pause of streaming when application minimizes
81200	Changed "Advanced Reporting" node to "Analytics" and moved "Shift Analysis/Employee Exceptions" to VPOS node.
80778	Added Analytics Object reporting to VIGIL Client
79161	Added ability to launch POS window from any camera during playback and not only the priority camera
79160	Added setting to close all open playbacks/live when launching a new POS playback from VPOS Search and VPOS Exceptions
79159	Moved the Forward/Backward Frame skip button from the edges of scrub bar to main playback control bar.
79158	Converted the "Cue Frame" feature to an optional setting (Settings > Playback Tab)
79157	Made the Quick Search window persist after a search is performed and results are viewed
77950	Added support for ANPR data (Live ANPR, ANPR Playback, ANPR Search, ANPR Alarms)
569	Copying a file from the Exports folder in Client now includes a copy of VIGIL DV player
Issues Fixed	
88214	Fixed issue where restricted video crashes vigil client when selected after export
87971	Fixed issue where the Virtual Switch status area still visible when disabled

www.3xlogic.com | helpdesk@3xlogic.com

© 2007-2024 3xLOGIC, Inc. All rights reserved. Information in this document is subject to change without notice. 3xLOGIC, and the 3xLOGIC/ VIGIL logos are trademarks of 3xLOGIC, Inc. All other trademarks are the property of their respective owners.

87190	Fixed issue where Client Settings windows is oversized when Virtual Switch is enabled
86877	Fixed issue causing inconsistent behavior with Client as Main UI's displayed cams on startup /w Virtual Switch active.
86789	Fixed issue where Remote Registration window not listing available things to register
86484	Fixed issue where remote client over VIGIL Connect relay cannot access the notes section for Alarm notifications
85968	Fixed issue where, with playback running, opening all live cameras then closing of them one erroneously suspends all live feeds
85599	Fixed issue where Client could not pull playback from some cameras that do not support encrypted communication
84883	Fixed issue where, in Windows 11, partially visible text was located adjacent to checkboxes in the Destination Settings > Media control window.
84548	Fixed issue where, when using "Use VIGIL Server Login" to get a list of Servers from VCM not all valid server groups/servers are displaying.
84425	Fixed issue where Use Server Export Destinations appears available even though Server and Client are not installed on same system
81829	Fixed issue causing a Socket Error while trying to access the Notes field in the Server alarms window with remote client over the relay server
81545	Fixed issue where some Audit Log functions show as ###F
81433	Fixed issue where Full Screen option in live feed context menu does not deploy live image in full-screen.
81208	Fixed issue where rendering camera streams are cycled through before all are eventually displayed as expected when the Display All option is double clicked in the treeview's <i>Cameras</i> node.
80829	Fixed issue causing VIGIL Client update to fail if VIGIL Client is in use.
80588	Fixed issue where Site Map - Display Site Map on Alarm fails.
80531	Fixed issue with Webview2 runtime causing Remote Web Browser in Client to display a blank page
80226	Fixed issue allowing users to save Emojis in Alarm Notes field, causing a '?' to be displayed in place of the emoji the next time the Alarm Notes are opened.
79904	Fixed issue where "Auto Detect Vigil Server" button does not allow selected servers to have an un-encryption option.
78109	Fixed issue causing unexpected layout grid when opening saved view with NVRs offline

VIGIL Central Management (VCM)

Ticket #. Issue/Enhancement

Issues Fixed	
84708	Fixed issue where the Reboot button fails to function on the Server Details page for standard users.
80853	Fixed issue where VCM Server and VCM Client failed to update if VCM Client was in use
80236	Fixed issue where VCM Start Menu options were differing depending on the install, package used
80081	Fixed issue where Settings snapshots for servers in the right click menu are greyed out, even though there are snapshots are available
80078	Fixed issue with Health Monitor refreshing when user is interacting with right-click menu.

VIGIL HD Viewer

Ticket #.

Issue/Enhancement

Issues Fixed

82245	Fixed issue causing persistent license expiry pop-up.
81175	Fixed issue where there is no languages available in Language Switcher window.
77750	Fixed issue where two shortcuts were created after upgrading the HD Viewer

www.3xlogic.com | helpdesk@3xlogic.com

© 2007-2024 3xLOGIC, Inc. All rights reserved. Information in this document is subject to change without notice. 3xLOGIC, and the 3xLOGIC/ VIGIL logos are trademarks of 3xLOGIC, Inc. All other trademarks are the property of their respective owners.

VIGIL Decoder Utility

Ticket #.	Issue/Enhancement
Issues Fixed	
72536	Fixed issue where Server channel numbers are being put into the OSD camera title
72535	Fixed issue where some VISIX Gen III cameras are showing as 'IP-Camera (ip address)'.
VICIL Video Diepley Metrix (VDM)	

VIGIL Video Display Matrix (VDM)

Ticket #.	Issue/Enhancement
Issues Fixed	
80557	Fixed issue causing erroneous ActiveX licensing prompt to deploy during installation of VDM.

www.3xlogic.com | helpdesk@3xlogic.com

© 2007-2024 3xLOGIC, Inc. All rights reserved. Information in this document is subject to change without notice. 3xLOGIC, and the 3xLOGIC/ VIGIL logos are trademarks of 3xLOGIC, Inc. All other trademarks are the property of their respective owners.