

#### VIGIL VMS 12.60.0100 - Full Release Notes

The following is a list of added features and issues fixed in the VIGIL Video Management System software suite between VIGIL v12.50.0000 (June 12<sup>th</sup>, 2023) and the new release of VIGIL v12.60.0100 (September 2023). Each VIGIL product will be listed with its fixed issues and added features contained beneath it in the table. Please contact 3xLOGIC Engineering Support if you have any questions or concerns.

## **Column Explanation:**

- Ticket #. The listed issue's reference number
- Issue/Enhancement Description of the issue/enhancement

## VIGIL Server - Includes VIGIL Video Verification, Media Server, VPOS, CLOUD NVR Plugin

Ticket #.	Issue/Enhancement
HICKEL#.	155uc/ Lilliancement

Added Features	
67186	Added channel number before all instances of camera name in VSMU.
66816	Added support for Hanwah device ONVIF DIO
66419	Renamed previous 360 Dewarping engine to "Legacy 360 Dewarping" in Camera Control settings menu.
66416	Added full support for VX-Vt-56-DUAL-X sensor selection to embedded camera detection tool.
65349	Updated AutoGas POS Parser to 2022-06-06 implementation
65170	Added "Detect" feature for ONVIF-based DIOs to quickly auto-populate input list / DO count in VIGIL
27953	Updated AvaloniaUI to v11
19661	Added original resolution support for MJP exports.
751	Added support for querying recording resolution of a specific camera to Media Server.
563	Implement Immerversion 360 Dewarping
558	Added support for VIGIL monitoring of VCA (Gen III Analytics capable cameras only) and added auto-reboot of VCA-enabled cameras if VCA failure is detected.
548	Revised Network Camera Settings form with added configuration options for newer VISIX and ONVIF-based cameras (on-camera settings accessed and edited via VIGIL)
517	Added pop-up dialogue informing users of required export destination formatting, when applicable.

#### Issues Fived

Issues Fixed	
68253	Fixed issue where, on systems with Client as Main Interface enabled that have updated, when VSMU is initially launched, VIGIL Client restarts unnecessarily.
68212	Fixed issue causing FPS of VISIX HD Analog cameras to be reported incorrectly to VCM or Client.
68014	Fixed issue causing analog multiplexor UI to fail to deploy.
67392	Fixed issue where Email address Masterlist "Edit" button adds new email instead of editing selection.
67025	Fixed issue where video analytics alarm emails are not sending
66954	Fixed issue where, after disabling the User Managed by VCM option in Server, settings changes cannot be applied in the VSMU settings form.
66912	Fixed issue where pre-alarm video settings for analytics alarm email notifications are not saving as expected.
66713 / 66413	Fixed issue where the VISIXIP Utility was failing to identify and preview multiple sensors on applicable cameras
66169	Fixed issue where Network Camera Settings URLs do not update when changing Camera Number for 3xLOGIC VISIX-IP-B
65808	Fixed issue where Video Loss Trigger section is getting cut off at the bottom
65788	Fixed issue causing VIGIL CLOUD NVR Plugin to send erroneous external requests regardless of if the plugin is used or not.
65660	Fixed issue causing Retalix parser to show Void in place of Return transaction items.
65390	Fixed issue causing Web Interface in Client to potentially fail to launch

65350	Fixed issue causing AM/PM options to disappear when scheduling still shots.
65346	Fixed issue where the Analog options slide bars fail to function
42907	Fixed issue causing VIGIL Scavenger to cause multiple silent unhandled exceptions
550	Fixed issue where starting a SIP audio-talk session crashes VIGIL Server Service
547	Fixed issue where, if Vigil Server Service is restarted during an active motion alarm, the alarm
347	does not get an end date and time
527	Fixed issue where RTSP URL were missing colons n the Network Camera Settings form
321	(though video still functioned as expected)
524	Fixed issue where VSMU failed to disable Email notification settings for configured mailboxes.
521	Fixed issue where updating an NVR registered as HIK with a failed capture card results in the
521	creation of thousands of invalid regkeys

# **VIGIL Client**

Ticket #. Issue/Enhanceme	Ticket #.	Issue/Enhancement
---------------------------	-----------	-------------------

## **Added Features**

Added support for bounding box (ALT + click and drag) digital zoom (digital zoom must be supported by camera).

#### **Issues Fixed**

133uc3 i ixcu	
68017	Fixed issue causing connection performance degradation for subsequent connections after initial client connection.
67790	Fixed issue where Close All Live function was causing unhandled exception.
66664	Fixed issue where Remote directory exporting crashes if you have any 2 or more checkboxes enabled
65986	Fixed issue where POS Quantity sections display differently on live and playback
65849	Fixed issue where POS IDX number had erroneously shifted to the first column
65386	Fixed isolated issue causing unhandled exception on Quick Export
546	Fixed isolated issue where Client User without proper permissions has access to Server Settings
523	Fixed issue causing Client to crash when changing column width on the Auto Detect VIGIL Server dialogue

# **VIGIL Central Management (VCM)**

Ticket #.	Issue/Enhancement
HICKET#.	155UE/EIIIIAIICEIIIEIIL

### **Issues Fixed**

68018	Fixed issue causing users with reduced server scope to have poorer UI and Server connection
08018	performance
66112	Fixed issue with Hard Drive Temperature Threshold not saving on multi-server edit
574	Fixed issue where VCM would allow the push of users without passwords to a site.

## **VIGIL Display Matrix (VDM)**

			_
Ticket #.	Is	sue/En	hancement

## **Issues Fixed**

**2841** Fixed issue causing H.265 video to display incorrectly

V12601RN-2 Updated: 9/22/2023